



SolidWorks 3, Assembly of a Castor

Part ID	Part name	QTY.
1	Base	1
2	Bracket	2
3	Bushing	2
4	Roller	1
5	Shaft	1
6	Washer	2
	98026A029	
7	Rounded Head screws	2
	90272A540	
8	Flat Head Screws	4
	90273A542	


Isometric view




Section view



Exploded view





6 | 5 | 4 | 3 | 2 | 1

D

A technical drawing showing a vertical profile with the following dimensions and features:

- Vertical height: 3.50
- Top horizontal distance: .50
- Top horizontal distance: .30
- Top horizontal distance: .50
- Left side horizontal distance: .50
- Bottom horizontal distance: R.25
- Bottom horizontal distance: 1.375
- Bottom horizontal distance: .25
- Bottom horizontal distance: .25

A technical drawing of a mechanical part, likely a bearing housing. The part has a top circular feature with a diameter of $\phi .50$ and a radius of $R.625$. Below this is a stepped shoulder with a radius of $R.25$ and a height of $.75$. The main body has a height of 2.875 and a shoulder radius of $R.25$. The bottom surface features three U-shaped cutouts with a width of $.50$ and a depth of $.50$. The overall width of the base is $.50$.

A 3D CAD model of a dark grey, triangular-shaped mechanical bracket. The bracket has a large central U-shaped cutout. It features two circular holes on the left side and a single circular hole on the right side. The top surface is flat, and the bottom surface is a solid dark grey. The model is shown from a perspective angle, highlighting its three-dimensional structure and internal features.

6


A technical drawing of a vertical pipe section. The pipe has a total height of 3.00, indicated by a vertical dimension line on the right. A horizontal dimension line shows a flange height of 2.00 from the base. Two circular features with cross-hatching, representing bolt holes, are located on the flange. A stepped support structure is shown to the right of the pipe.

1/4 Countersink
Flat Head Screw (82) —


UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN MILLIMETERS SURFACE FINISH: TOLERANCES: LINEAR: ANGULAR:		FINISH:	DEBURR AND BREAK SHARP EDGES	DO NOT SCALE DRAWING	REVISION
Units are IPS					
DRAWN	NAME	SIGNATURE	DATE	TITLE:	
CHK'D					
APPV'D					
MFG					
Q.A			MATERIAL:	Stainless Steel (Ferritic)	DWG NO.
			WEIGHT:	Bracket Drawing	
			SCALE:1:2	A4	
				SHEET 1 OF 1	

6 5 4 3 2 1

D



SECTION A-A



C

B

A

D


C

B

A

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN MILLIMETERS SURFACE FINISH: TOLERANCES: LINEAR: ANGULAR:		FINISH:			DEBURR AND BREAK SHARP EDGES	DO NOT SCALE DRAWING	REVISION
DRAWN	NAME	SIGNATURE	DATE				Units are IPS
CHK'D							
APP'D							
MFG							
Q.A.				MATERIAL: Copper			DWG NO.
				WEIGHT:			Bushing Drawing
				SCALE: 1:1			A4
				SHEET 1 OF 1			

6 5 4 3 2 1



6 | 5 | 4 | 3 | 2 | 1

D

D

Technical drawing of a mechanical part. The part has a central horizontal slot with a width of 2.10. On either side of this slot are two rectangular cutouts. The outer diameter of the part is 3.10. The inner diameter of the central slot is 0.675. The side cutouts have an outer diameter of 0.50. A chamfer of 0.05 at 45° is applied to the bottom edges of the side cutouts. The distance between the centers of the side cutouts is 1.00. The distance from the bottom of the central slot to the bottom of the side cutouts is 0.75. The top surface of the part is indicated by a dashed line.

SECTION A-A

— 1/4-20 Tapped Hole
Hole depth 1, Thread depth 0.75



6

C

B


B

A


A

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN MILLIMETERS SURFACE FINISH: TOLERANCES: LINEAR: ANGULAR:		FINISH:			DEBURR AND BREAK SHARP EDGES	DO NOT SCALE DRAWING	REVISION
Units are IPS							
DRAWN	NAME	SIGNATURE	DATE			TITLE:	
CHK'D							
APP'D							
MFG							
Q.A	MATERIAL: Stainless Steel (Ferritic)				DWG NO.	Shaft Drawing	A4
					SCALE:1:1		
	WEIGHT:				SHEET 1 OF 1		


**The Solidworks designs of the following parts can
be downloaded from McMaster Carr website**



Flat Head Screws
McMaster
Part# 90273A542



Washer
McMaster Carr
Part# 98026A029



Rounded Head Screws
McMaster Carr
Part# 90272A540

Steps for Assembly

- 1) Once you start a new assembly, insert the **Base** as the first part.
- 2) In this step, we want to align the local X-Y-Z coordinate system of this Base with the global X-Y-Z coordinate system of the entire assembly. To realize this, we need to mate the local front plane, top plane, and right plane of the Base with the global front plane, top plane, and right plane of the assembly. Before the mates of the three pairs of planes can be done, we will need to enable this part to float; otherwise it is fixed. To do so, right click the Base in the feature tree, and then select “**Float**”. After performing the mates between the two front planes, two top planes, and two right planes, respectively, the local X-Y-Z coordinate system of this Base is aligned with the global X-Y-Z coordinate system of the assembly. Now we can change this part from float back to fix (by right clicking the Base in the feature tree, and then selecting “**Fix**”).
- 3) In this step, we will assemble the two **Brackets** with the **Base**. Insert two of the Bracket components. To assemble each Bracket with the Base, we can perform three mates: mate the bottom surface of the Bracket with the corresponding top surface on the Base (Coincident mate), and mate the holes on the Bracket with the holes on the Base (Concentric mate).
- 4) In this step, we will assemble the **Shaft** between the two **Brackets**. Insert the component of Shaft. To assemble this Shaft with the two Brackets, we can first mate the exterior round surface of one end of the Shaft with the interior round surface of the hole in a Bracket (Concentric mate), and then we can use the **Width** mate in the **Advanced Mates** to place the Shaft at exactly the middle of the two Brackets. The Width mate constrains a tab between two planar faces.
- 5) In this step, we will assemble the **Roller** on the **Shaft**. To achieve this, we can first mate the interior round surface of the hole in the Roller with the exterior round surface of the Shaft (Concentric mate), and then use the **Width** mate in the **Advanced Mates** to place the Roller at the exact center of the Shaft.
- 6) In this step, we will assemble the two **Bushings**. Insert two of the Bushing components. To assemble each Bushing, many ways can be followed. For example, we can mate two surfaces on the Bushing with the corresponding surfaces on the Roller (Concentric mate). Note that you can also consider using Coincident mates, depending on how you approach this.
- 7) In this step, we will assemble the two **Washers**. To assemble each washer, we can perform a coincident mate between the flat surface of the washer and the corresponding surface on the Bracket, and then perform a concentric mate between the hole of the washer and the hole at the end of the Shaft.
- 8) In this step, we will assemble the two **Rounded Head Screws**. To assemble each screw, we can perform a coincident mate between the flat surface on the screw and the corresponding surface on the washer, and then perform a concentric mate between the end circle of the screw and the hole in the Shaft.
- 9) In this step, we will assemble the four **Flat Head Screws**. To assemble each screw, we can mate the Countersink surfaces (in this way, one mate can finish this step of assembly).

By this step, all the parts have been assembled. To ensure that every part is assembled perfectly, we can apply a **Section View** before checking. Consider running an interference detection (see supplementary document on Interference Detection in Supplementary Help)

You can notice that the assembly is still “under defined”. This is reasonable as many parts (e.g. the Roller) in this assembly can still move which is its designed function.

Brief Steps to Set an Exploded View

- 1) Click “**ConfigurationManager**”, right select the assembly that you just created (e.g. Default [Castor Assembly]) and then click “**New Exploded View**”.
- 2) Select each part and then pull along the direction we want. We can also select a group of parts and move them together.
- 3) After all the explode steps are done, click OK.
- 4) We can now view this assembly in either Explode version or the Collapse version (by right click ExplView1, select either “Collapse” or “Explode”).
We can also view the “Animate collapse” or “Animate Explode” as a video.
To save the animation, we can save it as an AVI or other file type.